



CIS Exterior Wall, Wood Stud Backing | Inside Corner  
 Detail 05.02.07A Rev. 01/27/19